

May 21, 2025

REQUEST FOR QUOTATION

The **TOURISM PROMOTIONS BOARD** invites you to submit quotations for the item/s listed below:

RFQ No. : **TPB-RFQ 2025.05.139**
PR No. : **2025.05.021 (PAMS 2025.05.013)**

Requirements : **Corrective Maintenance Services for TPB Pool Vehicles – 2018 Honda City 1.5 CVT AT with Plate No. SAB5098 and Conduction No. EOQ306**

Quantity	Particulars	Estimated Unit Price	Total Cost (PhP)
1 lot	2018 Honda City 1.5 CVT AT with Plate No. SAB5098 Labor: <ul style="list-style-type: none"> • Replace Stabilizer Link Front Both • Replace Front Shock Absorber Unit Both • Replace Gasket and Reseal Oil Pan • Perform Wheel Alignment • Replace Rear Crankshaft Oil Seal • Replace Oil Seal Torque Converter • Replace Oil Seal, Driveshafts (AT) Right • Replace Oil Seal, Driveshafts (AT) Left • Replace Shock Absorber Unit Rear Both • Replace Gasket and Reseal CVT Oil Fan • Replace Valve PCV • Perform Throttle Body & EDR Cleaning + Parts and Miscellaneous	PhP71,320.97	PhP71,320.97
1 lot	2018 Honda City 1.5 CVT AT with Conduction No. EOQ306 Labor: <ul style="list-style-type: none"> • Replace Lower Arm Lower Front Both • Replace Stabilizer Link Front • Replace Front Stabilizer Bush Holder Both • Replace Front Shock Absorber Unit Both • Replace Let LID Light Bulb • Perform Wheel Alignment Adjust • Replace Gasket and Reseal Oil Pan • Crankshaft Transmission Oil Seal, Right Side • Replace Oil Seal Torque Converter • Replace Oil Seal, Driveshafts (AT) Right 	PhP67,200.35	PhP67,200.35

	<ul style="list-style-type: none"> • Replace Oil Seal, Driveshafts (AT) Left • Replace Gasket, Reseal CVT Oil Pan + Parts and Miscellaneous		
	NOTE: 1. Quotation - All entries must be typewritten on your company letterhead. 2. Price Validity shall be for a period of thirty (30) calendar days.		
Terms	30 days from receipt of Invoice		
ABC	The approved budget for the contract (ABC) inclusive of applicable taxes		PhP138,521.32

Please submit your **quotation together with the duly accomplished Technical Compliance and the relevant documents enumerated below** to email address bhong_ducusin@tpb.gov.ph / bac_sec@tpb.gov.ph not later than **26 May 2025 at 5:00 PM**


Following are the relevant documents:

1. PhilGEPS Registration Certificate
2. Mayor's/ Business Permit
3. BIR Certificate of Registration (BIR FORM 2303)
4. Statement of Compliance to the Technical Specification (Annex "A")

For any clarification, you may send an email to the BAC Secretariat at the addresses stated above.

Please be informed that the Tourism Promotions Board is evaluating our suppliers' performance based on these criteria: Quality (40%), Cost (25%), Timeliness (25%), and Customer Service (10%)

Thank you very much.



JANET G. VILLAFRANCA

Acting Head, Procurement Management Division
Finance Department

Contact person: Jose T. Ducusin, Jr.

<u>TECHNICAL SPECIFICATION</u>			
Bidders must state "Comply" or any equivalent term in the column "Bidder's Statement against each of the Individual parameters of each Specification			
Item	Description	Total Quantity	Bidder's Statement of Compliance (comply /not comply)
	Corrective Maintenance Services for TPB Pool Vehicles - 2018 Honda City 1.5 CVT AT with Plate No. SAB5098 Labor: <ul style="list-style-type: none"> • Replace Stabilizer Link Front Both • Replace Front Shock Absorber Unit Both • Replace Gasket and Reseal Oil Pan • Perform Wheel Alignment • Replace Rear Crankshaft Oil Seal • Replace Oil Seal Torque Converter • Replace Oil Seal, Driveshafts (AT) Right • Replace Oil Seal, Driveshafts (AT) Left • Replace Shock Absorber Unit Rear Both • Replace Gasket and Reseal CVT Oil Pan • Replace Valve PCV • Perform Throttle Body & EDR Cleaning + Parts and Miscellaneous	1 lot	
	Corrective Maintenance Services for TPB Pool Vehicles - 2018 Honda City 1.5 CVT AT with Conduction No. EOQ306 Labor: <ul style="list-style-type: none"> • Replace Lower Arm Lower Front Both • Replace Stabilizer Link Front • Replace Front Stabilizer Bush Holder Both • Replace Front Shock Absorber Unit Both • Replace Let LID Light Bulb • Perform Wheel Alignment Adjust • Replace Gasket and Reseal Oil Pan • Crankshaft Transmission Oil Seal, Right Side • Replace Oil Seal Torque Converter • Replace Oil Seal, Driveshafts (AT) Right • Replace Oil Seal, Driveshafts (AT) Left • Replace Gasket, Reseal CVT Oil Pan + Parts and Miscellaneous	1 lot	

I hereby certify to Comply with all the above Technical Specifications.

Name of Company/Bidder

Signature over Printed Name of Representative

Date